

**DAKSHIN HARYANA BIJLI VITRAN NIGAM**

**Instruction No. 4/MON/2006**

From

The Xen/Monitoring,  
DHBVN, Hisar

To

All C.Es (OP)/S.Es(OP)XENs /SDOs (OP)/  
JEs-I, Incharge in DHBVN.

Memo No:-Ch.13/MON-260

Dated:-13.09.2006

**Subject: 70% loading of Distribution Transformers.**

It has been noticed that a large number of distribution transformers are damaged in the field regularly and no proper investigation for the cause of damage is being done by field officers. In this way a great loss of revenue is caused to the Nigam due to the frequently damage of distribution transformers.

It has been decided by the management that the maximum load allowed to the distribution transformer shall be 70% so as to protect the Distribution Transformers from damage. As such, it is requested to direct the field officers/officials under your kind control to comply with the above instructions meticulously failing which disciplinary action will be taken against them.

**Xen/Monitoring,  
DHBVN, Hisar**