

DAKSHIN HARYANA BIJLI VITRAN NIGAM
Vidyut Sadan, Vidyut Nagar, Hisar-125005

Sales Instruction No. 18/2007

From

GM/Commercial,
DHBVN, Hisar.

To

All CGMs/GMs/DGMs/AGMs (OP)
JE-I I/c Sub offices in DHBVNL

Memo No. Ch-18/GM/C/18/2007

Dated: 20/4 /2007

Subject: - Fixing of responsible for by passing the MCCB of DTs.

To curb the damage rate of DTs in DHBVN, MCCB have been installed on the DT for their protection against damage.

It has come to the notice of management that MCCBs installed on DTs are being by passed by the maintenance staff of the Nigam. Which is not a healthy practice. It has been decided that M&P organization will immediately check up these cases, & will inform to in writing to GM (OPs) concerned for fixing necessary responsibilities of the concerned maintenance staff. GM Ops shall take appropriate action, including recovery of the damage cost.

The above instructions should be brought to the notice of all concerned for careful and meticulous compliance.

-sd-
G.M./Comml.,
For C.G.M/Comml., DHBVN, Hisar