

Copy of the above is forwarded to the following for information please:-

Sales Instruction No. 15/2015

From

SPS to Addl. Chief Secretary (Power) / Chairman, HPU  
SPS to MD, DHBVN, Hisar  
SPS to MD, UHBVN, Vidyut Sadan, Sector-6, Panchkula  
SPS to MD, HVPNL, Sector-6, Shakti Bhawan, Panchkula  
PS to Director/OP and Project, DHBVN, Vidyut Sadan, Hisar  
PS to Director/OP and Project, UHBVN, Vidyut Sadan, Sector-6, Panchkula  
The Bays 33-38, Sector-6, Panchkula-134112, Haryana

To

Director/Vigilance, HVPNL, Shakti Bhawan, Sector-6, Panchkula  
LR, HPU, Shakti Bhawan, Sector-6, Panchkula  
Chairman, GGRF, DHBVN, Hisar  
All CEs/SEs/XENs/SDOs/OP,  
JEs-I, Incharge Sub office, in DHBVN,

**Memo No. Ch-15/SE/Comml./R-17/Loose/26/2015**  
**Dated: 8/9/2015**

**Subject: Recording of MDI reading for temporary connections without exception.**

It has been brought to the notice of the Management that MDI readings to detect extension in load especially in case of temporary connections are not being recorded by the field offices. During test checking got carried out by Enforcement wing it has been observed that there is large scale concealment of load in temporary connections resulting into loss of huge revenue of DHBVN. This situation could have been averted had the MDI reading been taken by the meter reading agency.

As such it has now been decided that all SEs (Op) shall ensure that henceforth MDI readings for all the temporary connections are recorded by the respective Meter Reading Agency without any exception. The MDI of all the temporary connections, particularly in Gurgaon & Faridabad Circle be got checked within 15 days and for all other circles within 10 days.

The above instructions may be brought to the notice of all concerned for strict and meticulous compliance.

*[Signature]*  
08/09/2015  
**CE/Commercial**  
**DHBVN Hisar.**