## DAKSHIM HARYAMA BIJILI VITRAN NIGAM

From

Instruction No. 68/MON/2020

The Coordinator, DHBVN, Hisar-

To

All CEs (OP)/\$E./(OP)/XENs (OP)/SDOs(OP)

JEs-I Incharge in DHBVN.

Memo No: Ch-124/MON-260/V-XII

Dated: 08.07.2020.

Subject:

Standard Operating Procedure (SOP) for dealing with cases of illegal encroachment / construction and extended Chhajjas by

the consumers in line with the Nigam instructions.

WTD UHBVN in its meeting held on 12/05/2020 discussed the Fatal/Non-Fatal accident cases for the month of March-2020 and observed that Fatal/Non Fatal accident cases of private persons have been increased as compared to corresponding previous year. One of the main reasons of accidents was found due to unauthorized extension of building / structure / projection/ balcony/ Chajja @Boundary wall etc. under/near 33 KV & 11 KV lines.

Nigam has however already issued latest sales circular No. D-3/2020, vide which it has been decided to immediately identity all such unauthorized construction / extension/ houses/ building / structures / projections / balconies/ Chajja/ Boundary walls etc. which are prone to electrical accidents and issue notice immediately directing the violator to remove the unauthorized within 15 days of receipt of the notice failing which criminal proceedings be initiated against him under section 488 of the Indian penal code, 1860 as well as section 133 of criminal procedure code 1973.

As per the directions of WTDs meeting dated 12.05.2020, the following Standard Operating Procedure (SOP) has been decided for dealing with cases of illegal encroachment/construction and extended chajjas by the consumers by UHBVN vide Dy. Secretary, Project Memo Ch-40/DSP-27/Vol-X dated 18.05.2020

- 1. All SDOs (OP) will give fresh Notice to owners who have constructed houses/building/structures/projections/balconies/Chajja/Boundary walls etc near/under the line irrespective of notice already given to them.
- 2. If in the given time of notice, owner fails to remove the illegal Construction/Structure near/under the line, criminal proceedings be

initiated against the owner under section 188 of the Indian penal code, 1860 as well as section 133 of criminal procedure code 1973 as per prevailing instructions of the Nigam Sales Circular No. D-3/2020.

- 3. FIR u/s 304 A or 337/338 IPC must be lodged in each and every electrocution case where accidents occur due to illegal/unauthorized Construction/Structure irrespective of blood relation with the deceased.
- 4. In case, Police authority refused to lodge the FIR, SDO (OP) shall proceed to file complaint in the court of the Judicial Magistrate/Metropolitan Magistrate u/s 156(3) read with Sec. 190 of the Criminal Procedure Code, 1973 praying for registration of FIR by the Police and investigation pursuant thereof.

The matter has been considered by DHBVN and decided to implement the above Standard Operating Procedure in DHBVN also. Accordingly all SE's/XEN's/SDO's (OP) are requested to comply with the above directions/ procedure with immediate effect in their area.

This issues with the approval of Director/OP, DHBVN, Hisar.

Coordinator, DHBVN, Hisar

Endst.No Ch-124/MON-260/Vol-XII

Dated:- 08.07.2020.

Copy of the above is forwarded to the following for information please:-

- 1. SPS to CMD, DHBVNL, for kind information of worthy CMD please.
- 2. SPS to Director (OP), DHBVNL for kind information of Director please.
- 3. SPS to Director/Projects, DHBVNL for kind information of Director please.
- 4. CE/HR&Admn., DHBVNL, Hisar
- 5. CE./P&D, DHBVNL, HIsar.
- 6. CE /MM, DHBVNL, Hisar.
- 7. CE /Commercial, DHBVNL, Hisar.
- 8. CFO, DHBVNL, Hisar.
- 9. CAO/MM, DHBVN, Hisar.
- 10. Chief Auditor, DHBVNL, Hisar.
- 11. Chief Accounts Officer, DHBVNL, Hisar.
- 12. SE/M&P, DHBVN, Hisar.
- 13. SE/IT, DHBVNL, Hisar. He is requested to incorporate the same on DHBVNL, Web site for updating the web site
- 14. XEN/Enforcement, DHBVN, Hisar/Gurgaon/Faridabad.
- 15. CCO, DHBVN, Hisar.

Coordinator, DHBVN, Hisar