

DAKSHIN HARYANA BIJLI VITRAN NIGAM

Instruction No.- 12 /2006/PD&C

From

The Chief Engineer/PD&C,
(Plg. & Design), DHBVN, Hisar.

To

All C.E.s(OP) in DHBVNL.
All S.E.s(OP) in DHBVNL

Memo No.Ch-29/DD-169

Dated : 27.7.2006

Sub : Earthing of Distribution Transformers.

During the Operational Review meeting dated 17.6.2006 held at Hisar, it was noticed that the damage rate to distribution transformers is higher due to improper and incomplete earth.

It has been decided to provide the proper earth to the Distribution Transformers, wherever earthing already provided, is either incomplete / damaged / not workable.

The earthing system be provided upto the ground water level, maximum 100 ft. only.

The certificate for ground water level is to be obtained block-wise from Agriculture Department of Haryana.

The standard design for earthing of DTs is placed at WEBSITE of DHBVN.

The rates for providing the earthing shall be decided by the respective S.E.s / Xens'(OP) after completing the usual formalities as per Nigam's instructions.

The payment shall be made after due checking from M&P Wing of the Nigam.

This issues with the approval of Whole Time Directors of DHBVNL.

**Chief Engineer/PD&C,
DHBVN, Hisar.**

Copy to the :

1. SPS to M.D., DHBVNL, Hisar for kind information of the M.D. please.
2. SPS to Director /Projects/(OP), DHBVNL, Hisar for kind information of the Directors please..
3. Chief Engineer (MM), DHBVNL, Hisar
4. S.E., Const. Circle, DHBVNL, Hisar.
5. DGM/IT, DHBVNL, Hisar for placing the same on WEBSITE.