

Damage Rate

(1) The position of transformers damaged during 08/2018 is

Name of Circle	No. of Transformer installed	Transformers Damaged			% Damage rate excluding	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	15121	99	36	135	0.65%	0.89%
Palwal	16221	142	178	320	0.88%	1.97%
Gurugram-1	16055	68	40	108	0.42%	0.67%
Gurugram-2	10416	77	31	108	0.74%	1.04%
Narnaul	20718	169	149	318	0.82%	1.53%
Rewari	21045	134	108	242	0.64%	1.15%
Bhiwani	41453	319	238	557	0.77%	1.34%
Hisar	21946	163	147	310	0.74%	1.41%
Fatehabad	34490	253	118	371	0.73%	1.08%
Sirsa	43938	289	136	425	0.66%	0.97%
Jind	32963	268	268	536	0.81%	1.63%
DHBVN	274366	1981	1449	3430	0.72%	1.25%

(2) The position of transformers damaged during 08/2017 is given as under:-

Name of Circle	No. of Transformer installed	Transformers Damaged			% Damage rate excluding	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	14389	106	35	141	0.74%	0.98%
Palwal	15491	91	122	213	0.59%	1.37%
Gurugram-1	13195	65	36	101	0.49%	0.77%
Gurugram-2	10170	59	33	92	0.58%	0.90%
Narnaul	20011	130	100	230	0.65%	1.15%
Rewari	20422	115	100	215	0.56%	1.05%
Bhiwani	39551	269	151	420	0.68%	1.06%
Hisar	21120	145	122	267	0.69%	1.26%
Fatehabad	33604	274	112	386	0.82%	1.15%
Sirsa	43169	264	98	362	0.61%	0.84%
Jind	29501	222	204	426	0.75%	1.44%
DHBVN	260623	1740	1113	2853	0.67%	1.09%

Name of Circle	No. of Transformer installed	Transformers			% Damage rate excluding	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	15121	505	149	654	3.34%	4.33%
Palwal	16221	679	655	1334	4.19%	8.22%
Gurugram-1	16055	304	142	446	1.89%	2.78%
Gurugram-2	10416	324	171	495	3.11%	4.75%
Narnaul	20718	712	486	1198	3.44%	5.78%
Rewari	21045	511	384	895	2.43%	4.25%
Bhiwani	41453	1156	686	1842	2.79%	4.44%
Hisar	21946	672	468	1140	3.06%	5.19%
Fatehabad	34490	1214	438	1652	3.52%	4.79%
Sirsa	43938	1399	507	1906	3.18%	4.34%
Jind	32963	1428	1130	2558	4.33%	7.76%
DHBVN	274366	8904	5216	14120	3.25%	5.15%
(3) The Cumulative position of transformers damaged for the year 2018-19 (upto 08/2018) is given as under:						
(4) The Cumulative position of transformers damaged for the year 2017-18 (upto 08/2017) is given as under:						
Name of Circle	No. of Transformer installed	Transformers Damaged			% Damage rate excluding	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	14389	722	148	870	5.02%	6.05%
Palwal	15491	496	455	951	3.20%	6.14%
Gurugram-1	13195	340	177	517	2.58%	3.92%
Gurugram-2	10170	251	185	436	2.47%	4.29%
Narnaul	20011	585	432	1017	2.92%	5.08%
Rewari	20422	460	351	811	2.25%	3.97%
Bhiwani	39551	1016	602	1618	2.57%	4.09%
Hisar	21120	705	419	1124	3.34%	5.32%
Fatehabad	33604	1204	392	1596	3.58%	4.75%
Sirsa	43169	1283	480	1763	2.97%	4.08%
Jind	29501	1206	855	2061	4.09%	6.99%
DHBVN	260623	8268	4496	12764	3.17%	4.90%